

10/505343




FIG 1






FIG 2

10/505343

FIG 3FIG 4a




Fig 4f




Fig 4b




Fig 4c




Fig 4d







Fig 4e

10/505343

FIG 5aFIG 5cFIG 5b

10/505343




FIG 6




FIG 7

10/505343




FIG 8a




FIG 8b

10/505343




FIG. 9

10/505343






FIG. 10

10/505343




1) EXTREME LEFT POSITION:
NO FLOW THROUGH HEATER
CIRCUIT AND
NO FLOW THROUGH RADIATOR
CIRCUIT.

FIG. 11A



2) INTERMEDIATE POSITION:
FLOW THROUGH HEATER
CIRCUIT,
NO FLOW THROUGH RADIATOR
CIRCUIT.

FIG. 11B



3) EXTREME RIGHT POSITION:
NO FLOW THROUGH HEATER
CIRCUIT,
FLOW THROUGH RADIATOR
CIRCUIT.

FIG. 11C

10/505343

FIG 12